

AGING WIRING INSPECTION REPORT ON PC-9/A
17 SEPTEMBER 2007

TABLE OF CONTENTS

Executive Summary	5
References:	8
Introduction.....	8
Background	8
Report Layout.....	8
Definitions and Abbreviations	9
Aging Wiring Inspection Program Objectives.....	10
Requirements of PC-9/A Inspection.....	10
Methodology.....	10
Aircraft Inspected.....	11
Relevant History	16
Aircraft Designer and Certification Basis.....	16
Original Equipment Manufacturer (OEM).....	16
Aircraft Age.....	17
Aircraft Hours	18
Wire Types Used.....	18
Detailed Inspection.....	18
Age Related Deterioration	18
Insulation Deterioration	19
Corrosion	20
Perished Cable Bushing.....	23
Aged Cable Clamps and Defective Cable Straps	25
Wiring in Pristine Condition.....	27
Wiring Husbandry.....	32
Contamination	32
Mechanical Damage.....	35
Chafing.....	37
Missing Connector Contacts	41
Unprotected Connectors.....	42
Connector Contacts.....	45
General Wiring Husbandry.....	45
Design Issues	46
Separation Distances	46
Use of Self Clinching Straps	49
Discussion and Analysis of Detailed Inspection	50
Criticality of Wiring Systems	50
Discussion of Age Related Deterioration.....	51
Insulation Deterioration	51
Corrosion	51
Perished Cable Bushings	52
Aged Cable Clamps and Defective Cable Straps	52
Wiring in Sound Condition.....	52
Discussion of Wiring Husbandry Related Issues.....	52
Compliance with ADF Aircraft Wiring and Bonding Manual.....	52
Contaminated Wiring.....	53
Chafing	55
Protection of Connectors with Dust Caps.....	55

Environmental Sealing of Connectors	56
Summary Wiring Husbandry	56
Discussion of Design Issues	56
Wire Separation Distances	56
Lacing and Tying and Use of Self Clinching Cable Straps	57
Training	58
Conclusions	58
Specific Conclusions	58
Determination of the Integrity of PC-9/A Wiring Systems	58
Determination if Wiring Systems Will Affect PC-9/A LOT	59
Aging Wiring Training	59
General Conclusions	60
Contractual Requirement to Comply with ADF Aircraft Wiring and Bonding Manual and Avionics Cleaning, Corrosion Control and Prevention Manual	60
Training on AAP7045.002-1 ADF Aircraft Wiring and Bonding Manual	60
Chafing in Conduit	60
Use of Incorrect Self Clinching Cable Straps	60
Recommendations	60
Compliance with AAP7045.002-1 and AAP 7002.033	60
Training	61
Design Changes	61
Chafing Inspection	61
Approved Alternatives	61
Aging Wiring Inspection Program	61